

Motorola Solutions Technical Notification (MTN)

TITLE: Remote Speaker Mic (RSM) PMMN4099 incorrect information in users guide

TECHNOLOGY: APX PMMN4099

SYMPTOMS:

RSM PMMN4099B User Manual instructed the user to speak into the RSM towards the mic port area as per Figure 1.



Figure 1: RSM User Manual instruction for user to speak

MODELS / SYSTEM RELEASES / KITS / DATECODES AFFECTED:

PMMN4099 - Date Code 1817 (Week 17, Year 2018) and before

SEVERITY RECOMMENDATION:

Low / Maintenance - Perform if system exhibits above symptoms

ROOT CAUSE / DEFINITIVE TEST:

The user manual incorrectly instructed the user to speak through the Mic Port

WORKAROUNDS AND CORRECTIVE ACTIONS:

Corrected the RSM User Manual to instruct the user to speak through the RSM Speaker as per Figure 2.



Figure 2: Corrected RSM User Manual instruction for user to speak

RESOLUTIONS AND REPAIR PROCEDURES:

Corrected User Manual shall be implemented on the RSM with Date Code 1818 and after.

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This Motorola Technical Notification (MTN) is issued pursuant to Motorola's ongoing review of the quality, effectiveness, and performance of its products. The information provided in this bulletin is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola disclaims any and all liability for product quality or performance if the recommendations in this MTN are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised, that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. ©2016 Motorola Solutions, Inc. All rights reserved."

PARTS REQUIRED (HARDWARE/SOFTWARE):

NA

ADDITIONAL INFORMATION:

NA

REFERENCE THE FOLLOWING DOCUMENTS/PROCESSES FOR INSTALLATION PROCEDURES:

NA

WHEN TO APPLY RESOLUTION:

After reboot
After (re)installation
After upgrade
After power cycle
After database restoration
After failure
On FRU replacement
During maintenance
Immediately
As instructed
Information only

LABOR ALLOWANCE:

This is an informational bulletin. No labor warranty is implied, intended or authorized for U.S. Domestic Partners/Customers. Other regions should follow their own standard procedures.

For assistance with this bulletin please contact your MSI Technical support centre

https://www.motorolasolutions.com/en_us/support.html

